






FLAT BELT PROFILES



CLEATED BELT PROFILES



EASY REMOVAL OF PROFILES



Several of our profile options include solid UHMW strips which are easily removed from the conveyor for sanitation by pulling pins on each end.

All pins are tethered to the frame to aid in sanitation.